

03500.013765



PATENT

Cole

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
HIDEKAZU TAKAHASHI)
Appln. No.: 09/384,973)
Filed: August 30, 1999)
For: PHOTOELECTRIC CONVERTING)
APPARATUS HAVING AMPLIFIERS)
WITH DIFFERENT GAINS FOR ITS)
SENSOR AD STORAGE UNITS)
U.S. Patent No.: 6,989,863 B1)
Issued: January 24, 2006)

Examiner: James Hannett
Art Unit: 2612
May 25, 2006

Certificate
MAY 31 2006
of Correction

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

05/26/2006 SZEWDIE1 00000095 6989863

01 FC:1011


100.00 OP

MAY 31 2006

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentee' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

A handwritten signature in black ink, appearing to read 'J. A. Krause', written over a horizontal line.

John A. Krause
Attorney for Patentee
Registration No. 24,613

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200
570561v1

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,989,863 B1

DATED : January 24, 2006

INVENTOR(S) : HIDEKAZU TAKAHASHI

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON COVER PAGE AT (54) TITLE

"AD" should read --AND--.

COLUMN 1

Line 3, "AD" should read --AND--.

COLUMN 4

Line 27, " C_{SM} "} $\cdot G_{DCM}$ " should read -- C_{SM} "} $\cdot G_{DCM}$ --.

COLUMN 5

Line 25, " -2_T " should read -- $2N_T$ --; and
Line 26, " $(-2N_T+n_M)$." should read -- $(-2N_T+N_M)$ ---.

COLUMN 6

Line 63, " ϕ_{CR} ," should read -- ϕ_{GR} --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,989,863 B1

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

570561v1



31 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,989,863 B1

DATED : January 24, 2006

INVENTOR(S) : HIDEKAZU TAKAHASHI

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON COVER PAGE AT (54) TITLE

"AD" should read --AND--.

COLUMN 1

Line 3, "AD" should read --AND--.

COLUMN 4

Line 27, " C_{SM} "} $\cdot G_{DCM}$ " should read -- C_{SM} "} $\cdot G_{DCM}$ --.

COLUMN 5

Line 25, " -2_T " should read -- $2N_T$ --; and

Line 26, " $(-2N_T + n_M)$." should read -- $(-2N_T + N_M)$.--.

COLUMN 6

Line 63, " ϕ_{CR} ," should read -- ϕ_{GR} --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,989,863 B1

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

570561v1



81 4006

Staple
Here
Only!

PRINTER'S TRIM LINE